

BUILDINGS & GROUNDS DEPARTMENT

FACILITIES COMMITTEE MEETING

Capital Project Building Priority List Review 2015 - Building Condition Survey High School Middle School Clarence Center Elementary Harris Hill Elementary Sheridan Hill Elementary Ledgeview Elementary **Transportation Buildings & Grounds**

HIGH SCHOOL

Handicap Locker Room Benches (Item 7)






g Shutte





















MIDDLE SCHOOL







FACILITIES C

* Relocate Acid








CLARENCE CENTER





12

A COUNTY OF A PROPERTY

FACILITIES C

* Kitchen Serv



tem 31)



HARRIS HILL







SHERIDAN HILL



- Flooring Replacement (Item 45)
- Masonry Restoration (Item 47)
- Bathroom Flooring (Item 47)

Identical to Harris Hill so I will spare you the photos.



LEDGEVIEW









FACILITIES C

Replace Ast



- Transportation Parking Lot (Item 49)
 - + I would recommend a drive through for the full experience. Pictures do not convey this issues with the existing asphalt.
 - × Pot Holes
 - Depressions from Wheels
 - × Poor drainage and subgrade

QUESTIONS?